

**Fatalities & Accidents FY 2011
Austin & San Antonio Area Offices**

<p>10-6-10</p>	<p>Atomic Security, Inc DBA Asi Protection Services Co. Size: 6 SIC: 1731 Age: 40 Hispanic: N</p>	<p>Austin</p>	<p>Worker was installing one of three security cameras on the roof of a one story building when he fell to his death. He was working alone, and at the time of the fall was using a roof as a working surface of 9 feet in height. He had installed a security camera using a step ladder to reach the work. When he fell off of the roof he struck a bicycle rack at ground level. The accident happened at about 01:30 pm.</p>
<p>10-26-10</p>	<p>IMT Residential Co. Size: 100 SIC: 6513 Age: 57 Hispanic: Y</p>	<p>Austin</p>	<p>Groundskeeper was riding in a golf cart on his way to get his golf cart. The cart he was riding in reached his golf cart and he stepped out. He grabbed a bucket of trash as he exited the cart and lost his balance. He struck his head and later died of his injuries.</p>
<p>11-17-10</p>	<p>Star Transport, Inc. Co. Size: 10000 SIC: 4731 Age: Hispanic:</p>	<p>Temple</p>	<p>Worker died in the cab of his truck, most likely of natural causes.</p>
<p>11-19-10</p>	<p>Western States Fire Protection Co. Co. Size: 200 SIC: 1711</p>	<p>Austin</p>	<p>Laborer was painting pipe while standing on a step ladder. He fell approx. 6 feet (2 m)</p>

	Age: 50 Hispanic: Y		and struck his head on the concrete floor. He died later in the hospital for head injuries.
12-19-10	L.W. McDonald Co. Size: 1 SIC: 1731 Age: Hispanic:	Boerne	Electrocution from attempting to install a 600 Amp, 3 phase 480/277 V, 4 wire, type 3R main disconnect on a utility pole. The worker fell from a ladder leaned against the utility pole.
12-22-10	Global Electric Co. Size: 27 SIC: 1731 Age: 52 Hispanic: Y	Austin	A Worker was electrocuted when working on connecting lights to electrical power. Worker was working on live wires intentionally since the breaker that needed to be switched off that controlled the lights also controlled other circuits in the building, affecting building tenants.
1-27-11	Jesus Denova Santamaria Co. Size: 8 SIC: 1721 Age: 25 Hispanic: Y	Austin	On 01/27/2011, at approximately 4:15 PM, two employees fell approximately 30 feet to the ground when the work platform they were standing on, tipped off of the forks of a Sky Trak, rough terrain forklift. The work platform was a trash box unit not approved by the forklift manufacturer for lifting personnel. One worker died in the fall, and one was

			injured.
2-28-11	International Bancshare Corp. Co. Size: SIC: Age: Hispanic:	San Antonio	Worker walking on an elevated catwalk died when he fell nearly 12 feet through an unsecured access door.
4-13-11	Austin Distributing Co. Size: 55 SIC: 3492 Age: 50 Hispanic: N	San Antonio	Worker fixing a hydraulic fluid leak was killed after the front end loader collapsed, pinning the worker between the machine and the loader's bucket.
4-26-11	The Other Place Co. Size: 15 SIC: 7011 Age: 46 Hispanic: Y	New Braunfels	Employee entered Comal river to cut down a rope swing that was hanging down from an overhanging low lying limb. He stepped off into a very deep water hole and drowned as he could not swim and there were no swimmers to help.
5-6-11	Great American Insulation, Inc. Co. Size: 3 SIC: 5033 Age: 19 Hispanic: Y	Taylor	On May 5, 2011 at approximately 2:50pm an employee of Great American Insulation, Inc. climbed out of the delivery/cargo work truck that was parked at a residential intersection. Instead of walking around the truck to get to the opposite side, the worker rolled under the cargo bed between the front and rear wheels of the vehicle. The driver of the truck, unaware of the

			<p>employee under the vehicle, began moving forward. The driver's side, rear dual wheels struck the employee from his heels to his head, causing massive trauma.</p>
6-1-11	<p>Ringo Drilling Co. Size: 309 SIC: 1381 Age: 25 Hispanic: Y</p>	Ozona, TX	<p>An employee was fixing a leak on a centrifugal pump below the mudhouse on drilling rig #17. The employee finished fixing the leak and opened the electrical panel box that controlled the centrifugal pump when he came in contact with an energized 480 volt circuit and was electrocuted.</p>
6-22-11	<p>Ridgeway Electric Co. Size: 4 SIC: 4911 Age: 28 Hispanic:</p>	Ozona, TX	<p>On June 22, 2011, an employee was preparing to repair a downed powerline. One line had been shut down, however the downed line came into contact with a live line that had not been shut off. When employee reached for the downed line he was electrocuted. He was pronounced dead the same day.</p>
6-28-11	<p>Herzing Roofing LLC Co. Size: 25 SIC: 1765 Age: 37 Hispanic: Y</p>	Universal City	<p>An employee removed fall protection equipment from the top of a 5 to 12 pitch roof that was in the process of being renovated. The employee walked to the top of the roof and</p>

			<p>removed the anchorage point, ropes and then walked to the edge and threw the equipment to the ground. The employee started to walk back to the top of the roof when he started sliding on the water barrier material and could not maintain his balance and fell 19 1/2 feet sustaining fatal injuries.</p>
7-15-11	<p>Con-Way Freight Ltd. Co. Size: 23000 SIC: 4231 Age: 49 Hispanic: Y</p>	San Antonio	<p>The forklift operator was moving a crate with unknown equipment out of a trailer and into the dock. The crate was 98" tall X 64" deep, X 36" wide and top heavy. The Freight Classification Specialist was examining freight on the dock, when the forklift operator moved forward out of the trailer next to the Freight Classification Specialist. The load became unstable and tipped over, fatality injuring the Freight Classification Specialist.</p>
7-27-11	<p>Jetka Steel Erection Co. Size: 6 SIC: 1791 Age: 30 Hispanic: Y</p>	San Marcos	<p>A connector was crushed when the scissor lift from which he was working was struck by the collapsing building. Workers were attempting to place purlins on the fabricated steel</p>

